

# Oil Field Environmental Incident Summary

**Incident:** 20170620154629

**Date/Time of Notice:** 06/20/2017 15:46

**Responsible Party:** Creek Energy Services

**Well Operator:** HANNA SWD, LLC

**Well Name:** 2230 Offload 1

**Field Name:** EAGLE NEST

**Well File #:**

**Date Incident:** 6/20/2017

**Time Incident:** 10:30

**Facility ID Number:** 700139-01

**County:** DUNN

**Twp:** 148

**Rng:** 95

**Sec:** 1

**Qtr:** SE NW

**Location Description:** Offload Lane 5 and 6

**Submitted By:** Ron Martin

**Received By:**

**Contact Person:** Corwin Saurdiff  
5910 N CENTRAL EXPY STE 630  
DALLAS, TX 75206

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 100 Feet

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	3	Barrels	3	Barrels		
Other						

**Description of Other Released Contaminant:**

Production salt water

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

none

**Areal Extent:**

Produced water ran about 2 truck lengths and puddled, sucked up all water off hard driveway.

**Potential Environmental Impacts:**

none

**Action Taken or Planned:**

water was vacuumed / cleaned / scrapped immediately

**Wastes Disposal Location:** Little Knife Disposal

**Agencies Involved:**

**Updates**

---

**Date:** 6/20/2017    **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary this spill occurred within the MHA nations boundaries. Forwarded to BIA/Tribal authorities.